

**Figure 1 Photograph Looking Towards The Northern Part of The Site**



**Figure 2 Photograph of Southern Part of Site Looking North West**



**Figure 3 Collection of Photographs Highlighting Potential Sources of Contamination**

(a) Waste tank which appears to have emptied its contents on site (b) rusting metal on the ground (c) and (d) containers which could potentially contain highly flammable liquids (e) and (f) general waste and scrap and (g) a container which housed a fire suppression system.

Figure 4: Photographs of embankment slopes around mounded southern part of the site (a) east-side (b) north-side (c) west-side (d) south-side



**Figure 4 Photographs of Embankment Slopes Around Mounded Southern Part of Site**



(a) east-side (b) north-side (c) west-side (d) south-side