


We inspire
with energy.



We are rethinking energy.
Rethink your safety.



The 8 main MVV identified risks



Hot Work

Obtain authorisation and a permit to work. A second person should always fire watch and always wear the personal protective equipment.



COSHH/Waste

Don't touch if not necessary, read datasheet and COSHH risk assessment and wear correct personal protective equipment.



Work at Height

Obtain authorisation and a permit to work and protect yourself against a fall when working at height.



Plant Machinery

Maintain inspection and maintenance. Stay on designated walkways, wear high-viz clothing and make sure the driver sees you when crossing.



Isolation

Obtain a permit to work, authorisation and verification that work can be undertaken without hazard from electrical or mechanical equipment.



Fire and Explosion

No smoking on site and be cautious near explosive areas. Maintain and inspect all firefighting equipment.



Confined Space

Obtain authorisation and a permit to work before entering a confined space and have a topman for supervision.



Lifting Equipment

Know how to use it and check for damage before lifting and be aware of ongoing lifting operations.



MVV Environment Devonport Ltd

Devonport EfW CHP Facility
Creek Road
Plymouth
PL5 1FL

Jane Ford
Community Liaison Manager
M +44 7876 135 632

Alex Whittle
QHSE Manager
M +44 7976 174 162

Emergency number
Control Room 24hrs
T +44 1752 393 155

MVV Environment Ridham Ltd

Ridham Dock Biomass Facility
Lord Nelson Road
Ridham Dock, Iwade
Sittingbourne, ME9 8FQ

Kevin Souster
Facility Manager
M +44 7557 569 291

William Gillman
QHSE Manager
M +44 7780 454 969

Emergency number
Control Room 24hrs
T +44 1795 342 212

MVV Environment Baldovie Ltd

Baldovie EfW CHP Facility
Forties Road
Dundee
DD4 0NS

Mimi Mwasame
Community Liaison Manager
M +44 7966 216 041

Gregor McGhee
QHSE Manager
M +44 7970 156 662

Emergency number
Control Room 24hrs
T +44 1382 483 605

