Noise Monitoring Steering Group

Site – 1st May 2013 2pm – 4pm

Present:

John WadeJurgen FolzConstruction Director, MVVSite Manager, Envi-Con

Gregg Portass
 Graham Hooper
 Public Protection Service, PCC
 Public Protection Service, PCC

• Daniel Ellis URS

• Jane Ford Community Liaison Manager, MVV

(minutes)

• Caroline Leatherdale Environmental Manager, Kier/MVV

Apologies:

Nicola Horne
 Public Protection Service, PCC

• Alf Maneylaws URS

David Mudge
 Environment Agency

ITEM		ACTION
1.	Introductions, present and apologies	
	As above	
2.	Confirmation of agenda	
	Agenda was agreed	
3.	Minutes of last meeting	
	Minutes of last meeting have been discussed and agreed	
	 Actions arising TR circulated supplementary noise monitoring data to JF. Distributed to NMSG MVV to review accuracy of complaints record. This was clarified. 	
4.	Noise monitoring report	
	Monitoring since the last meeting was carried out on the following dates: - 3 rd April 2013 - 18 th April 2013 - 24 th April 2013 - 1 st May 2013 Noise levels varied between 47 and 63dB New activities on site are piling in the area of the new bridge	

	and pre-assembly of bag filter units. 12 piles are being installed and this work is likely to last for approximately two weeks. Assembly of bag filter units is likely to last for a further three weeks. Most recent monitoring captured the new activities and noise levels were found to be still within agreed limits. Monitoring to be continued on the following dates: - 15/16 th May 2013	
5.	- 29/30 th May 2013 - 12/13 th June 2013 - 26/27 th June 2013	
J.	Site actions and updates	
	Limited excavation works around piles and foundations.	
	Construction works for floor slabs and walls - Ongoing.	
	Preassembly of bag filters — ongoing (see above).	
	Minor steel work installation is anticipated to begin in middle of May 2013. Major steel work installation is scheduled to start in middle of June 2013.	
	Details of additional mitigation measures issued 01/05/13 to LPA.	
	Acoustic screens have been placed prior to the start of piling. Noise monitoring has been carried out.	
	It was noted that the larger, mobile screens were not appropriate in this position due to access restrictions, however insulated screens have been deployed on top of a spoil batter closest to the piling rigs. The building concrete structures are also beginning to provide some additional mitigation.	
6.	Complaints	
	One noise complaint received by MVV since the last noise monitoring meeting. This related to reversing alarms on vehicles on Saturday 20 th April. Site management have confirmed that all of the vehicles for which this is possible have been fitted with 'white noise' reversing alarms instead.	MVV

7.	AOB	
	Date of next meeting:	
	4 th June 2013 @ 10:00	